

India Street Force Main Condition Assessment

UIC 2026 for Registered Attendees Only
Unauthorized Reproduction or Distribution Prohibited



2/28/2026




India Street Force Main

- High risk asset
- Pipe traverses downtown Portland and high tourism area (including cruise ship port)
- 7,024 feet of PCCP constructed in 1976
- 33" diameter lined cylinder pipe
- Interpace corporation, Hudson, NY plant (Class III wire)




Eastern Promenade Walking Trail



Common PCCP Force Main Failure Modes

- External deterioration: Corrosion and hydrogen embrittlement related damage of prestressing wire (wire breaks)
- Internal corrosion: H₂S corrosion at gas pocket locations
- Overloading: Excessive overburden or excessive pressure loading
- Debris: Debris up constricts pipeline flow



Project Criteria

- Determine pipe reliability
 - Pipe wall assessment
 - Sonar profiling- debris
 - Acoustic survey- leaks and gas pockets
 - Pressure monitoring- C Factor, loading
- **Pipe must remain in service at all times**
- Condition Assessment Solution:
 - XK1- free swimming multi sensor inspection
 - High frequency pressure monitoring
 - Visual inspection of discharge chamber



XK1 Inspection Device

Stabilizers (centers inspection device)

Acoustic sensor (leaks and gas pockets)


Sonar (debris and gas pockets)

Electromagnetic sensors (broken wire wraps)


Sail (propels device)



Insertion of Inspection Device



Ready for Launch!



Tracking the Inspection Devices



Capturing Inspection Device

Safety top priority



Custom built extraction rack




Inspection device arrives at extraction



Electromagnetic Signals


- Pipes without damage provided consistent repeatable signal
- One pipe reported with broken wire wraps (est. 5 BWW)



Findings of Sonar Profiling

- 14 locations with debris build up
- Largest debris pile was 30 feet long with maximum depth of 5.6 inches
- Small debris pile reported was 2-inches deep, 2 feet long
- No gas pockets detected

Sonar data



Debris depth = 5.6"


33" diameter circle

Findings of High Speed Pressure Monitoring

- Pressure monitoring:
 - Operating and transient transients were within allowable limits
 - Two surges detected, (below allowable limit)

Table 7: Pressure Data Summary

Design Working Pressure	85 psi
Maximum Allowable Transient Pressure	119 psi
Average Dry Weather Pressure	16.1 psi
Average Wet Weather Pressure	37.6 psi
Maximum Recorded Pressure	76.7 psi



Other Condition Related Data

- Pipe designed for E-80 (rail loading) but loading is vehicular or foot traffic
- Although pipe constructed in 1970s, Class III prestressing wire was utilized
- Operating pressure (wet weather) 38 psi; design operating pressure 80 psi

Variables contributing to improved structural performance

Table 3. India Street Force Main Design Specifications (Original Contracts)

Contract Number	5		3	
Manufacturer	Interpace		Interpace	
Year Constructed	1976		1976	
Inside Diameter (in)	33		33	
Pipe Classes	N/A		A	B
Core Thickness (in)	2-1/16		2-1/16	
Minimum Coating Thickness (in)	13/16		13/16	
Wire Size	#8		#8	
Prestressing Wire Class	III		III	
Wire Area (in ² /ft)	0.280	0.320	0.165	
Wraps Per Foot	13.59	15.53	8.00	
Ultimate Tensile Strength (psi)	262,000		262,000	
Gross Wire Wrapping Stress (psi)	196,500		196,500	
Dynamometer 1 wire (lb)	4,050		4,050	
Design Pressure (psi)	85		85	
Maximum Design Depth of Cover (ft)	15	15	6	
Live Load	H-20	E-80	H-20	
Concrete Strength at Wrapping (psi)	3,500	3,700	3,500	
Cylinder Thickness (in)	0.0449		0.0449	

UIC 2026 for Registered Attendees Only
Unauthorized Reproduction or Distribution Prohibited

Findings

- Force main is in good condition with little evidence of deterioration. Should have long remaining life.
- One pipe identified with broken wire wraps.
 - 0.3% of project pipe
 - National average is 3.9% (pipe is performing better than average)
- Loading conditions well under design
- No gas pockets or leaks
- 14 locations with debris build up

UIC 2020 for Registered Attendees Only
Unauthorized Reproduction or Distribution Prohibited

Recommendations

- Investigate root causes of surge and mitigate
- In the future, if debris build up affects hydraulics, remove debris
- If pipeline modifications are performed, sample wire and mortar coating
- Reinspect in 7 years to evaluate growth in deterioration

UIC 2026 for Registered Attendees Only
Unauthorized Reproduction or Distribution Prohibited

Happy Project Team (Portland Water District, Insight Water Technologies, HDR)!



INSIGHT



Questions

Please visit: [India Street Wastewater Force Main Condition Assessment - Portland Water District](#)

Or contact:

- PWD's Project Manager, Helen Newman, at (207) 523-5279 or hnewman@pwd.org or
- HDR's Project Technical Lead, Mike Higgins at mike.higgins@hdrinc.com

UIC 2026 for Registered Attendees Only
Unauthorized Reproduction or Distribution Prohibited