



Let's Go Deeper DWU's Cedar Crest Water Line Replacement

Justin Reeves PE, LEED AP



- 72-Inch AWWA C301 (PCCP) Pipe
- 1989 Installation
- Located in South Dallas
- Crossing of the Trinity River
- Catastrophic Pipeline Failure



Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



- 72-Inch AWWA C301 (PCCP) Pipe
- 1989 Installation
- Located in South Dallas
- Crossing of the Trinity River
- Catastrophic Pipeline Failure



Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



- 72-Inch AWWA C301 (PCCP) Pipe
- 1989 Installation
- Located in South Dallas
- Crossing of the Trinity River
- Catastrophic Pipeline Failure



Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



- 72-Inch AWWA C301 (PCCP) Pipe
- 1989 Installation
- Located in South Dallas
- Crossing of the Trinity River
- Catastrophic Pipeline Failure



LARGE WATER MAIN BREAK Near I-45 -- South of Downtown Dallas

March 4-6, 2025 | Houston, TX

Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



- 72-Inch AWWA C301 (PCCP) Pipe
- 1989 Installation
- Located in South Dallas
- Crossing of the Trinity River
- Catastrophic Pipeline Failure



Near I-45 -- South of Downt, wir Dulla

Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



- Emergency Response
- Pipe Repair Performed
- Bank "Stabilization" Completed
- Temporary Solution
- Pipe Remained Compromised



Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.




- Emergency Response
- Pipe Repair Performed
- Bank "Stabilization" Completed
- Temporary Solution
- Pipe Remained Compromised



Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.





Design Criteria

Maintain Service •

Consider Master Plan •

Do Not Transfer Thrust •

Provide Isolation •

Construction Risk •


* CELEBRATING

30

YEARS

Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



Design Decisions

Offset Alignment (Service) •

84-Inch Diameter (Master Plan) •

AWWA C200 Steel Pipe (Thrust) •

Owner Procured Valves (Isolation) •

Vertical Drop (Risk) •

* CELEBRATING

30

Underground Infrastructure Conference


Construction. Rehabilitation. Asset Management.

Vertical Drop

- Clayey Sands to 40-ft
- Seams or Fractures to 70-ft
- Stable Material at 85-ft
- Secant Pile Shafts

Risk

- Short Lifts of CLSM Backfill
- Lean Concrete Behind Tees



Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.




Vertical Drop

- Clayey Sands to 40-ft
- Seams or Fractures to 70-ft
- Stable Material at 85-ft
- Secant Pile Shafts

Risk

- Short Lifts of CLSM Backfill
- Lean Concrete Behind Tees



Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



Valve Procurement

- 84-Inch Diameter
- Rubber-Seated Butterfly Valve
- Provided by Crispin Valve, LLC
- 250-PSI Rated Working Pressure
- EPDM Seats




Isolation



Construction. Rehabilitation. Asset Management.








* CELEBRATING

30

YEARS

Project Challenges





Underground Infrastructure Conference

Construction. Rehabilitation. Asset Management.



Tunnel Complete

Carrier Pipe Installed

Current Status

Going "Vertical"

Preparing for Shut Down | Tie-In







Questions?

Justin Reeves PE, LEED AP

JReeves@lan-inc.com

