Underground Construction Technology | Jan. 29-31, 2019 | Fort Worth, TX

Reuse/Sanitary Sewer Extended Along Frisco, TX Commercial Corridor

Clayton C. Barnard, P.E.








Project Location – Frisco, TX





Demographics – Frisco, TX





Underground Construction Technology | Jan. 29-31, 2019 | Fort Worth, TX

1999

•Reuse Authorization obtained


2001

- •Constructed Reuse P.S. at Stewart Creek WWTP and Transmission Line
- •Trails Golf Course connects (1 MGD)

2007

- •PSV's added to Pressurize System
- •2 additional customers connected (Greenbelt Park & Pearson's Farms development)

Original Reuse System





Reuse System After Panther Creek

THE **UNDERGROUND** UTILITIES EVENT

Underground Construction Technology | Jan. 29-31, 2019 | Fort Worth, TX

2009


 Constructed Reuse P.S. at Panther Creek WWTP

2012

• B.F. Phillips Park connected to reuse system

2014


 Constructed Transmission Line from Panther Creek Reuse P.S. to System





Underground Constructi







Reuse System After Panther Creek

THE **UNDERGROUND** UTILITIES EVENT

- 2 Pump Stations
- 10 Active Customers









North Platinum Corridor






Underground












Undergro



This Photo by Unknown Author is licensed under CC BY-SA










Horizontal Directional Drill





Horizontal Directional Drill

Nominal Depth, feet bgs			Detailed Description of Soils/Materials	
Top of Layer	Bottom of Layer	General Description	Encountered	
B-01				
0	20	Fat Clay Lean Clay	Stiff to hard, Fat Clay with Sand (CH) / Lean Clay with Sand (CL) / Fat Clay (CH).	
20	30	Weathered Shale	Soft, Weathered Shale.	
B-02				
0	1	Fill	Hard, Clayey Sand (SC) / Sandy Lean Clay (CL) Fill.	
1	5	Weathered Limestone	Soft to hard, Weathered Limestone.	
5	13	Limestone	Very hard, Limestone.	
13	45	Shale	Soft, Shale.	
B-03				
0	2	Fat Clay	Very stiff, Fat Clay with Sand (CH).	
2	7	Weathered Limestone	Hard, Weathered Limestone.	
7	30	Limestone	Very hard, Limestone.	

Project Bidding - Reuse




- Advertised Date: July 2015
- Estimated Project Cost: \$3 million
- Bid Date: July 28, 2015
 - 3 bids were received
- FPVCP was sole sourced for the HDD

Bid Item	Description	Quantity	Unit			
A. Reuse Water Line						
15	Jack, Bore, or Tunnel (Steel Casing)(20")	1,079	LF			
16	Reuse Water Line – 12" DR18 PVC (Horizontal Directional Drill)	2,451	LF			











































Horizontal Directional Drill Force Main









Project Bidding – Force Main

- Advertised Date: May 2017
- Estimated Project Cost: \$8 million
- Bid Date: June 12, 2017
 - 5 bids were received
- FPVCP was sole sourced for the HDD

Bid Item	Description	Quantity	Unit			
B. Force Main						
2	Jack, Bore, or Tunnel (Steel Casing)(36")	2,238	LF			
3	Force Main – Fusible PVC (DR 18)(20")(Horizontal Directional Drill)	2,637	LF			




Geotechnical Information

Nominal Depth, feet bgs			Detailed Description of Soils/Materials	
Top of Layer	Bottom of Layer	General Description	Encountered	
B-01				
0	20	Fat Clay Lean Clay	Stiff to hard, Fat Clay with Sand (CH) / Lean Clay with Sand (CL) / Fat Clay (CH).	
20	30	Weathered Shale	Soft, Weathered Shale.	
B-02				
0	1	Fill	Hard, Clayey Sand (SC) / Sandy Lean Clay (CL) Fill.	
1	5	Weathered Limestone	Soft to hard, Weathered Limestone.	
5	13	Limestone	Very hard, Limestone.	
13	45	Shale	Soft, Shale.	
B-03				
0	2	Fat Clay	Very stiff, Fat Clay with Sand (CH).	
2	7	Weathered Limestone	Hard, Weathered Limestone.	
7	30	Limestone	Very hard, Limestone.	


THE UNDERG

THE **UNDERGROUND** UTILITIES EVENT



Construction- Force Main







Construction- Force Main





Construction - Overview

THE **UNDERGROUND** UTILITIES EVENT

- ~2,500 LF Reuse HDD in 1 pull
 - Pipe was fused in one length
- ~2,700 LF SSFM HDD in 1 pull
 - Two intermediates were required
- Minimal traffic control
 - Brief 1-lane shutdowns for material and equipment drop-offs
- Challenge:
 - Curvilinear alignment on the SSFM HDD

- Trenchless installation minimized disruption to the surface feature
- Suitable soil condition and availability of sufficient working area contributed to the success of the project
- HDD proved to be a time and cost efficient method
- Drilling through rock formation yielded extremely stable bore hole



THANK YOU

- Art Hartle, PE
 - ahartle@friscotexas.gov
- Clayton C. Barnard, PE
 - Clayton.barnard@freese.com





