Debris Removal Solutions

SHARED EXPERTISE + UNIQUE TECHNOLOGY = INNOVATIVE SOLUTIONS

HOW DID THAT GET IN THERE?

CLEANING INFLUENT AND RETURN
CHANNELS AT CORPUS CHRISTI'S
OSO WATER RECLAMATION PLANT

CAUSES

- 30 + YEARS WITHOUT CLEANING
- 20 YEARS WITHOUT GRIT CATCHER
- 20 YEARS WITHOUT BARSCREEN
- RUNNING AT CAPACITY—NO SHUTDOWN
- NEAR OVERFLOWS


EMERGENCY CLEANING 2017 95 Cubic Yards Removed




CONSTRUCTION 2018

- NEW HEADWORKS
 - Grit Catcher
 - Bar Screen
 - Channel Cleaning
 - 1420 Tons







CHANNEL IS 17' DEEP



AIR GUNS BREAK UP RAGS

















BOLSENA SLUDGE PUMP
















POLYMER TEST



INJECTING POLYMER TO STREAM







Phase Separator





POLYMERIZED MATERIAL


















FIRST BOX HEADED TO LANDFILL 9.2 TONS



FLOATING GREASE AND RAGS



RAGS IN MANIFOLD



RESULTS

- 2468 TONS REMOVED
 - APPROXIMATELY 2,100 CUBIC YARDS CAPACITY RECLAIMED
 - 45 TONS OF GREASE
 - 11 TONS OF RAGS
- PLANT REQUIRES ONE LESS BLOWER
 - SAVINGS OF \$90,000 PER YEAR

Wayne Brown

(832) 621-9221

wayne@debrisremovalsolutions.com

Debris Removal Solutions

SHARED EXPERTISE + UNIQUE TECHNOLOGY = INNOVATIVE SOLUTIONS